

**Flood Control Project Maintenance
Levee Inspections**

2014 Channel Summary Report

Overall Unit and Item Ratings

Placer County

Truckee River

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance**Unit Cover Sheet**
2014 Channel Inspection Results**Placer County**

Channel
Truckee River

Channel Rating	A
Date of Inspection	07/02/2014
DWR Inspector	John Williamson
Accompanied By	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View

Outlet Structure / Up

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		39.167060 °
Category	Rivers, Channels & Designated Flood			-120.143950 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_1			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Rating **	A	Issue No.	1 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.167060 °
Category	Rivers, Channels & Designated Flood			-120.143950 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_1			

Rating **	A	Issue No.	1 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.167060 °
Category	Rivers, Channels & Designated Flood			-120.143950 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_1			

Photo 1 of 3 : CH_2014_NA0045_13_1_20140703_00013.jpg



The water is shallow coming out of Lake Tahoe. Summer 2014

Photo 2 of 3 : CH_2014_NA0045_13_1_20140703_00012.jpg



Looking upstream at the very low flow out of Lake Tahoe. Summer 2014

Photo 3 of 3 : CH_2014_NA0045_13_1_20140703_00011.jpg



Standing on the walkway looking upstream at Lake Tahoe. Summer 2014

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View

Outlet Structure / Up (cont)

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		39.167060 °
Category	Rivers, Channels & Designated Flood			-120.143950 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_2			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		39.167060 °
Category	Rivers, Channels & Designated Flood			-120.143950 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_3			

Action/Comments

Inspector Comments: No head cutting or horizontal deviation observed.

No Photos

Rating **	N	Issue No.	4	GPS Lat/Long
Issue Type +	Ma	Location *		39.167060 °
Category	Rivers, Channels & Designated Flood			-120.143950 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_4			

Action/Comments

Inspector Comments: This item does not apply to this inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View

Outlet Structure / Up (cont)

Rating **	A	Issue No.	5	GPS Lat/Long
Issue Type +	Ma	Location *		39.167060 °
Category	Rivers, Channels & Designated Flood			-120.143950 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_5			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Outlet Structure / Down

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		39.167060 °
Category	Rivers, Channels & Designated Flood			-120.143950 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_6			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH_2014_NA0045_13_6_20140616_00002.jpg



A side view of the downstream side of the structure. Summer 2013

Photo 2 of 2 : CH_2014_NA0045_13_6_20140703_00014.jpg



Looking at the outlet structure from Highway 89. Summer 2014

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View

Outlet Structure / Down (cont)

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		39.167060 °
Category	Rivers, Channels & Designated Flood			-120.143950 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_7			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		39.167060 °
Category	Rivers, Channels & Designated Flood			-120.143950 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_8			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	N	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		39.167060 °
Category	Rivers, Channels & Designated Flood			-120.143950 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_9			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View

Outlet Structure / Down (cont)

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		39.167060 °
Category	Rivers, Channels & Designated Flood			-120.143950 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_10			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Hwy 89 / Up

Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		39.167160 °
Category	Rivers, Channels & Designated Flood			-120.143920 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_11			

Action/Comments

Inspector Comments: The flow going out the control structure is very low. Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH_2014_NA0045_13_11_20140703_00015.jpg



Looking upstream from Highway 89 at the outlet structure. Summer 2014

Photo 2 of 2 : CH_2014_NA0045_13_11_20140616_00003.jpg



From Highway 89 looking at the outlet structure. Summer 2013

Rating **	A	Issue No.	11 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.167160 °
Category	Rivers, Channels & Designated Flood			-120.143920 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_11			

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View

Hwy 89 / Up (cont)

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		39.167160 °
Category	Rivers, Channels & Designated Flood			-120.143920 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		39.167160 °
Category	Rivers, Channels & Designated Flood			-120.143920 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_13			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		39.167160 °
Category	Rivers, Channels & Designated Flood			-120.143920 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_14			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View				
Hwy 89 / Up (cont)				
Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		39.167160 °
Category	Rivers, Channels & Designated Flood			-120.143920 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_15			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Hwy 89 / Down				
Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		39.167160 °
Category	Rivers, Channels & Designated Flood			-120.143920 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_16			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH_2014_NA0045_13_16_20140703_00016.jpg



Looking downstream from Highway 89. Summer 2014

Photo 2 of 2 : CH_2014_NA0045_13_16_20140616_00004.jpg



Downstream of the Truckee River from Highway 89. Summer 2013

* Location LS : Land Side WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain			

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View

Hwy 89 / Down (cont)

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		39.167160 °
Category	Rivers, Channels & Designated Flood			-120.143920 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_17			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		39.167160 °
Category	Rivers, Channels & Designated Flood			-120.143920 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_18			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	N	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		39.167160 °
Category	Rivers, Channels & Designated Flood			-120.143920 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_19			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View

Hwy 89 / Down (cont)

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		39.167160 °
Category	Rivers, Channels & Designated Flood			-120.143920 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_20			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View

bike bridge / Up

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			120.147590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c _ 2012_21			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH_2014_NA0045_13_21_20140703_00017.jpg



Looking upstream from the bike bridge. Summer 2014

Photo 2 of 2 : CH_2014_NA0045_13_21_20140616_00005.jpg



An upstream look of the Truckee River. Summer 2013

Rating **	A	Issue No.	21 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			120.147590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_21			

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View

bike bridge / Up (cont)

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			120.147590 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_22			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			120.147590 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_23			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	N	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			120.147590 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_24			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View

bike bridge / Up (cont)

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_25			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

bike bridge / Down

Rating **	A	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			120.147590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_26			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH_2014_NA0045_13_26_20140703_00018.jpg



Looking downstream from the bike bridge. Summer 2014

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View

bike bridge / Down (cont)

Rating **	A	Issue No.	26 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			120.147590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_26			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 2 of 2 : CH_2014_NA0045_13_26_20140616_00006.jpg



A downstream look of the Truckee River. Rafters are having fun.
Summer 2013

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			120.147590 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_27			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			120.147590 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_28			

Action/Comments

Inspector Comments: No head cutting or horizontal deviation observed.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View

bike bridge / Down (cont)

Rating **	N	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			120.147590 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_29			

Action/Comments

Inspector Comments: This item does not apply to this inspection.

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_30			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Tahoe City lumber yard / Up

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_31			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 4 : CH_2014_NA0045_13_31_20140616_00007.jpg



Looking upstream from Tahoe City Lumber Yard. Summer 2013

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View

Tahoe City lumber yard / Up (cont)

Rating **	A	Issue No.	31 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_31			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 2 of 4 : CH_2014_NA0045_13_31_20140703_00020.jpg



The vegetation on the berm installed in 2011-12 is maturing. Summer 2014

Photo 3 of 4 : CH_2014_NA0045_13_31_20140703_00019.jpg



Looking upstream from Tahoe City Lumber Yard. Summer 2014

Photo 4 of 4 : CH_2014_NA0045_13_31_20140616_00008.jpg



The vegetation on the berm has grown protecting the embankment. Summer 2013

Rating **	A	Issue No.	31 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_31			

Rating **	A	Issue No.	31 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_31			

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View

Tahoe City lumber yard / Up (cont)

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_32			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_33			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	N	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_34			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View

Tahoe City lumber yard / Up (cont)

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_35			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Tahoe City lumber yard / Down

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_36			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH_2014_NA0045_13_36_20140703_00021.jpg



Looking downstream From Tahoe City Lumber Yard. Summer 2014

Photo 2 of 2 : CH_2014_NA0045_13_36_20140616_00010.jpg



Looking downstream from Tahoe City Lumber Yard. Summer 2013

Rating **	A	Issue No.	36 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_36			

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View

Tahoe City lumber yard / Down (cont)

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_37			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_38			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_39			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/02/2014 07/02/2014	John Williamson

Check Point / View			
Tahoe City lumber yard / Down (cont)			
Rating **	A	Issue No.	40
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Encroachments		
DWR ID	DWR_NA0045_13_c_2012_40		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement